
## COM-5003 -> USB or TCP-IP data receive throughput test


The throughput test can be performed over USB (COM-5003-A, personality index 2) or over TCP-IP (COM-5003-B, personality index 3)

1. Open the COM-5003 settings panel (3<sup>rd</sup> button from left). Select the throughput test.

Note: the IP address only matters if TCP-IP is used as the default medium.



2. Open the Functions | Receive File menu and select a file and file size (in bytes). Selecting a large file size makes it easier to time the transfer speed.



Successful capture:



3 As the received file is a binary file, you may need a binary viewer to check the contents (for example binary viewer freeware).

One can verify the file size and the file contents (no missing byte).

